



Middels dit bulletin willen wij informeren dat er een wijziging op de Ditting molens wordt doorgevoerd

**Stationary disc flange Art.No. 1008708**

De bovenste stationaire flens van de molen is aangepast. De maalschijven zijn als apart onderdelen te bestellen met artikelnummer 1005606.

De belangrijkste wijziging en verbetering van deze flens is:

- Een groef in de draad van de flens (ze foto)
- Minder vastlopen van de flens door vervuiling

| Oude versie                                                                        | Nieuwe versie                                                                       |
|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|  |  |

De flens is volledig backwards compatible.

Deze wijziging wordt doorgevoerd in week 16/2019.

Indien u nog vragen over dit bulletin heeft, aarzel dan niet om contact met ons op te nemen.




We would like to inform you that we will replace the Ditting stationary disc flange in our coffee machines with Ditting grinder.

**Stationary disc flange Art.No. 1008708**

The spare part contains the stationary disc flange only. Grinder blades are available with article number 1005606.

The main improvement of the stationary disc flange is:

- Dirt groove in the thread
- Less jammed flanges



The adapted Ditting stationary disc flange is fully backwards compatible. Existing spare parts on stock (old version) can be still used for all machines.

This change will be implemented from **CW16/2019**.

If you have any further questions, please do not hesitate to contact us.